

MC10 / Drawing atlas

Dimensions & installation

Independent views grouped by motor installation.

Drawing units are stated at the first page of each installation group.

Reference dimensions; confirm mounting and stroke for your configuration.

Use labelled dimensions; do not scale the drawings.

C outside

5 views | pp. 2-4

D inside

5 views | pp. 5-7

L left

4 views | pp. 8-10

R right

4 views | pp. 11-13

B lower

3 views | pp. 14-16


Product specifications and selection guidance are supplied separately.

For configuration-specific dimensions or actual CAD files, contact HTROBOT.


MC10 / C outside

Drawing dimensions in mm.


View 1



View 2




View 3




MC10 / C outside

Section Flange



MC10 / C outside


Installation overview




MC10 / D inside

Drawing unit unverified; original dimension labels are retained.


View 1



View 2




View 3




MC10 / D inside

Section Flange



MC10 / D inside


Installation overview




MC10 / L left

Drawing unit unverified; original dimension labels are retained.

View 1




View 2




MC10 / L left

Section Flange



MC10 / L left


Installation overview




MC10 / R right

Drawing unit unverified; original dimension labels are retained.

View 1




View 2




MC10 / R right

Section Flange



MC10 / R right

Installation overview



MC10 / B lower


Drawing unit unverified; original dimension labels are retained.

View 1



MC10 / B lower

Section Flange



MC10 / B lower

Installation overview

