



HOW TO USE THIS ATLAS

Each view is the catalog drawing for the stated variant or ratio group. Use the printed labels, not a scale measurement. These are reference drawings, not CAD files

EDA135 / Drawing atlas

CONTENTS

R01	1 views pages 2-2
L01	1 views pages 3-3

CONTACT HTROBOT


Email: emmy@htrobot.com

Website: www.htrobot.com

EDA135 | Dimension drawing

Catalog drawing

EDA135 R01 dimension drawing illustrate:L1=Scalable length+200,L2=Scalable length+480 | R01



EDA135 | Dimension drawing

Catalog drawing

EDA135 L01 dimension drawing illustrate:L1=Scalable | length+200,L2=Scalablelength+200,L2=Scalable | length+500length+500 | L01

